





ASSEMBLY INSTRUCTION








3
1
4
5
2
2
5

Parts List


1  1 PC	2  2 PCS	3  1 PC
4  1 PC	5  2 PCS	

Hardware List

A  M6X70mm 14 PCS	B  M6X30mm 4 PCS	C  M4 1 PC
D  4 PCS	E  4 PCS	F  4 PCS





philips head screw driver
required of assembly
(Not include)



electric drill
(Not include)

Step 1:








Note: The spacing of each layer can be adjusted.

A
M6X70mm
4 PCS


Step 2:







A

M6X70mm
10 PCS

Step 3:








B


M6X30mm
4 PCS

Step 4:



D

4 PCS
E

4 PCS
F

4 PCS